



Clothing measurements ABC for men’s clothing:

This page is here to help you find yourself the right kind of workwear, and to inform different size marking’s logic.

All of **ATEX**-workwear are formulated with C-lining, unless told otherwise.

Clothes are normally marked with letter and number sizes combined, and letter sizes separately.

- B-lining: Skinny
- C-lining: Normal
- D-lining: Stocky
- E-lining: Thick
- F-lining: Corpulent

MC- or C-lining is so called zero point, where every other measure is either + or – centimeter marked.

Two numbers in size mark after the letter mean the normal measure.

For example, C52 (generally 52) is so called standard measure made clothing, so C-lining and 52 size number.

Some of the **ATEX** workwear are marked with letters only. **Mainly** jackets, winter wear, overalls, shirts and vests are marked with **XS-6XL** labels.

Trading the letter size into numbers:

44	46	48	50	52	54	56	58	60	62	64	66	68	70	72	74	76	78	80
XS	S	M	L	XL	XXL	3XL	4XL	5XL	6XL									

The exact dimension table about chest- and waist measures, you can find from the **Dimension Table** –page.

Dimension tables are usually made that the measurements are persons’ firm body measures. So, measure for example your chest circumference and based on that, choose the right size of jacket from the chart. **ATEX** products have the extra loose centimeters already added in them.